

OFFICIAL ANNOUNCEMENT

October 2012

Notice of Production Discontinuation for Incandescent Light Bulbs for Buoy and Marine Beacons

In recent years, the transition to LED lighting has been accelerating rapidly across both residential and corporate sectors, driven in part by government-led initiatives.

To support our customers using existing legacy products, we have consistently urged light bulb manufacturers to maintain production. However, manufacturers are now completely discontinuing the production of these incandescent bulbs as of fiscal year 2012.

While we have historically supplied maintenance and replacement parts for incandescent marine lanterns currently in service, we have decided to officially terminate the supply of these incandescent replacement components. This transition will allow us to fully promote energy-saving, high-luminance solutions.

Although we may be able to fulfill some requests depending on our remaining parts inventory, please be advised that once specific component stocks are exhausted, we will provide an upgraded, comprehensive LED lantern assembly as a replacement.

Please note that all newly available products from our lineup are now fully standardized with LED technology. Regarding the transition of your existing equipment to LEDs, we offer tailored proposals depending on your specific model.

We kindly request that you contact your local authorized distributor or our sales office for further details.

Your understanding and continued cooperation are highly appreciated.

Inquiries Regarding This Matter:

Ryokuseisha Co., Ltd.

Sales Department

Phone: +81-3-5644-7950 (Main Line)

For email inquiries, please contact us via the contact form on our official website.

URL: <https://www.ryokuseisha.com>